1FW

g3500,014595 (35.C14595)

PATENT

No. Let	**************************************		
INF	2 9 7005 E IN THE UNITED STATES PATE	NT AN	ND TRADEMARK OFFICE
ATEMIS.	TRADEMARKS In re Patent of:)	Examiner: Y. Aggarwal
	YASUO SUDA	:)	Group Art Unit: 2615
	Appln. No.: 09/604,964)	Patent No.: 6,885,404 B1
	Filed: June 28, 2000)	Issued: April 26, 2005
	For: IMAGE PICKUP APPARATUS)	July 29, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

08/01/2005 HALI11 00000076 6885404 01 FC:1811

100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentee. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentee's undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010. All correspondence should be directed to our address given below.

Respectfully submitted,

Daniel S. Glueck

Attorney for Patentee Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DSG/llp

DC_MAIN 210027v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,885,404 B1

DATED

April 26, 2005

INVENTOR(S) :

Yasuo Suda

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4

Line 36, "diaphragm 10," should read --diaphragm 110,--. Lined 62, "the-image" should read --the image--.

COLUMN 5

Line 64, "10b," should read --100b,--.

COLUMN 14

Line 24, "G(2i1)" should read --G(2i+1)--. Line 55, "B(i-1)-j½" should read --B(i-1)-½--.

COLUMN 17

Line 49, "10b," should read --100b,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,885,404 B1</u>

No. of add'l. copies

No. of add'l. copies @ 30¢ per page

 \Rightarrow

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/Ip DC_MAIN 210029

Staple St

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,885,404 B1

DATED

April 26, 2005

INVENTOR(S) :

Yasuo Suda

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20

Line 38, "set" should read --set such that a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/Ib DC_MAIN 210029

PATENT NO. 6,885,404 B1

No. of add'l. copies @ 30¢ per page

